

Root Cause Investigation by Furukawa


Wobbling of the sensor in EPS Column

13/May/2004 Furukawa Electric Co.,Ltd.

1. Analysis of Warranty returned sensors.

13/May/04 FEC


1-3 Wobbling amplitude of sensor in EPS column (Fig6)



Confidential

2. Signal noise duplication during sensor wobbling

13/May/04 FEC



Confidential



2. Signal noise duplication during sensor wobbling

13/May/04 FEC


2-3 Spin test with competitor's sensor. (Fig 10)

Just reference: extreme stress test

This test not simulating actual vehicle condition.



— P1
— P2
... T1
- . T2



Confidential

13/May/2004 Furukawa Electric

Conclusion

1. We found no significant difference in performance between Low-Friction plating and Normal plating.
2. Root cause : Stick slip due to Combination of following items.
 - (1) Improper installation alignment of the sensor to EPS column. (not completely seated)
 - (2) Less robustness design of sensor compared with the competitor's.
Competitor : Single function (relative only)
Furukawa : Delphi required combined design
(relative and absolute)
3. Furukawa would like to have joint investigation with Delphi and GM to confirm further details.



Confidential

Root Cause Investigation by Furukawa

Conclusion: Wobbling of the sensor in EPS Column


FHGA-04010002 13/May/04 Furukawa Electric Co.,

1: Analysis of Warranty returned sensors






The wobbling amplitude of case was 0.66(deg) on average.

* Returned Sensors (N=4):
The Wobbling amplitude of EPS column returned to FEC was 0.66 degrees on average.



3: Sulfur detected on brushes of Warranty Sensors. (reference)


FEC performed EPMA analysis on the brushes of warranty returned sensors. Sulfur, which can be the cause of contact failures, was detected on warranty sensor brushes as shown in Fig 13. We have doubts that Sulfur is a contributing cause because we detected Sulfur on 3 sensors returned from Milford proving ground. However, we are investigating how the presence of Sulfur affects the reliability of the FEC contacting sensor.



2: Signal Noise duplication during Sensor Wobbling


Signal noise was produced when the sensor wobbled in Spin test.

The sensor rotors are rotated at maximum speed of 300 rpm for 100,000 rotations applying wobbling on purpose. The signals are continuously monitored without a low pass filter used in actual vehicles. The trigger level for detecting signal error is 6 times more stringent than the specification of the sensor. The probability of signal noise increases when the wobbling amount increases, as shown in Fig 7, 8. With normal plating, the tendency is the same. Fig 7 shows only the large noise incidents from Fig 8 data.



When the sensor is wobbling, the wires move side ways, and produce a stick slip motion.

Side ways motion can easily cause the stick slip of all wires resulting in an unstable contacting condition.



Competitor's sensor also produces signal noise when the brushes slip out of the sliding track. (reference)

This is extreme stress test

This test not is simulating actual vehicle

When we performed Spin test using competitor's sensor at FEC, significant signal noise was detected when the sensor was tilted at 1.3 degrees from the shaft. After changing the tilting angle to 0 degrees the noise disappeared. But the robustness of competitor's sensor is higher than FEC's. Probability of noise creation may be much lower than FEC's.

